



## Hi-Vis Cut E Gloves -10/XL -1pc

GANTS HAUTE-VISIBILITÉ ANTI-COUPURE 5/E - 10/XL - 1 PAIRE

- Haute visibilité dans un environnement à faible luminosité
- L'anti coupure 5 E, idéal pour de la tôle, la manutention de verre, du dénudage, la canalisation
- Gants léger et fin avec une couche de polyuréthane sur la paume, permettant une bonne dextérité
- Le revêtement en nitrile renforce la protection entre le pouce et les doigts.



## Hi-Vis Cut E Gloves -10/XL -1pc

GANTS HAUTE-VISIBILITÉ ANTI-COUPURE 5/E - 10/XL - 1 PAIRE

- Haute visibilité dans un environnement à faible luminosité
- L'anti coupure 5 E, idéal pour de la tôle, la manutention de verre, du dénudage, la canalisation
- Gants léger et fin avec une couche de polyuréthane sur la paume, permettant une bonne dextérité
- Le revêtement en nitrile renforce la protection entre le pouce et les doigts.



## Hi-Vis Cut E Gloves -10/XL -1pc

GANTS HAUTE-VISIBILITÉ ANTI-COUPURE 5/E - 10/XL - 1 PAIRE

- Haute visibilité dans un environnement à faible luminosité
- L'anti coupure 5 E, idéal pour de la tôle, la manutention de verre, du dénudage, la canalisation
- Gants léger et fin avec une couche de polyuréthane sur la paume, permettant une bonne dextérité
- Le revêtement en nitrile renforce la protection entre le pouce et les doigts.



## Hi-Vis Cut E Gloves -10/XL -1pc

GANTS HAUTE-VISIBILITÉ ANTI-COUPURE 5/E - 10/XL - 1 PAIRE

- Haute visibilité dans un environnement à faible luminosité
- L'anti coupure 5 E, idéal pour de la tôle, la manutention de verre, du dénudage, la canalisation
- Gants léger et fin avec une couche de polyuréthane sur la paume, permettant une bonne dextérité
- Le revêtement en nitrile renforce la protection entre le pouce et les doigts.



Article Number	4932479304
Care instruction	Washing, normal process, maximum washing temperature 40° Celsius; do not bleach; do not iron; no chemical cleaning; no tumbler
Care instruction symbols	Washing 40 degrees; No bleach; No iron; No chemical cleaning; No tumbler
Code couleur	Rouge
Conditionné par	1
Cut level	E
Dimensions	10 / XL
Emballage	Hang Card
Gauge (stitches / inch)	13



Article Number	4932479304
Care instruction	Washing, normal process, maximum washing temperature 40° Celsius; do not bleach; do not iron; no chemical cleaning; no tumbler
Care instruction symbols	Washing 40 degrees; No bleach; No iron; No chemical cleaning; No tumbler
Code couleur	Rouge
Conditionné par	1
Cut level	E
Dimensions	10 / XL
Emballage	Hang Card
Gauge (stitches / inch)	13



Article Number	4932479304
Care instruction	Washing, normal process, maximum washing temperature 40° Celsius; do not bleach; do not iron; no chemical cleaning; no tumbler
Care instruction symbols	Washing 40 degrees; No bleach; No iron; No chemical cleaning; No tumbler
Code couleur	Rouge
Conditionné par	1
Cut level	E
Dimensions	10 / XL
Emballage	Hang Card
Gauge (stitches / inch)	13



Article Number	4932479304
Care instruction	Washing, normal process, maximum washing temperature 40° Celsius; do not bleach; do not iron; no chemical cleaning; no tumbler
Care instruction symbols	Washing 40 degrees; No bleach; No iron; No chemical cleaning; No tumbler
Code couleur	Rouge
Conditionné par	1
Cut level	E
Dimensions	10 / XL
Emballage	Hang Card
Gauge (stitches / inch)	13

